


15064

AIRPORT DIAGRAM

AL-5320 (FAA)

BUCHANAN FIELD (CCR)
CONCORD, CALIFORNIA



SW-2, 20 AUG 2015 to 17 SEP 2015

SW-2, 20 AUG 2015 to 17 SEP 2015

AIRPORT DIAGRAM

15064

CONCORD, CALIFORNIA
BUCHANAN FIELD (CCR)

CITY/AIRPORT	HOT SPOT	DESCRIPTION
TUCSON TUCSON INTL (TUS)	HS 1 HS 2	Rwy 29R sometimes mistaken for Rwy 29L. Pilots instructed to hold short of Rwy 11L–29R or Rwy 11R–29L sometimes cross the apch area of these rwys without authorization.
CALIFORNIA		
ATWATER CASTLE (MER)	HS 1 HS 2	Complex area. Verify correct taxi route. Areas south of Twy A and Twy G are private ramp. Tfc congestion due to large volume of acft proceeding to and from Rwy 31.
CARLSBAD MC CLELLAN–PALOMAR (CRQ)	HS 1	ATC has difficulty seeing small acft taxiing eastbound on Twy A, when "Large Jets" are parked on the ramps.
CHINO CHINO (CNO)	HS 1 HS 2 HS 3	Pilots taxiing south on Twy D, sometimes fail to turn on to Twy A and proceed onto Rwy 08L–26R by mistake. Pilots taxiing west on Twy L, sometimes turn onto Rwy 03–21 by mistake. Pilots taxiing south on Twy K sometimes fail to turn onto Twy A and proceed onto Rwy 08L–28R by mistake.
CONCORD BUCHANAN FLD (CCR)	HS 1 HS 2 HS 3	Pilots departing the Rwy 32L run–up area sometimes mistake Twy J for Rwy 32L. Complex intersection at Rwy 01R–19L, Twy J, Twy A, Twy C and Twy K. Pilots on Twy A sometimes fail to comply with hold short instructions for Rwy 32L apch area and/or fail to proceed completely through Rwy 32L apch area when instructed by ATC.
HAWTHORNE JACK NORTHROP FLD/HAWTHORNE MUNI (HHR)	HS 1	Rwy 25 run–up area, do not depart the run–up area without ATC clearance.
HAYWARD HAYWARD EXECUTIVE (HWD)	HS 1 HS 2 HS 3 HS 4	Acft approaching Twy A from the ramp sometimes fail to turn onto Twy A, proceeding onto Twy E and ultimately Rwy 10L–28R. Area not visible from ATCT. Area not visible from ATCT. Area not visible from ATCT.
LA VERNE BRACKETT FLD (POC)	HS 1	Short distance between parallel Rwy 26R and Rwy 26L. Be aware of the rwy holding position markings for the parallel rwy and do not cross without authorization.
LANCASTER GENERAL WM J FOX AIRFIELD (WJF)	HS 1	Pilots taxiing from ramp sometimes mistake Rwy 06–24 for Twy A.
LIVERMORE LIVERMORE MUNI (LVK)	HS 1 HS 2 HS 3 HS 4 HS 5 HS 6	Pilots instructed to hold short of Rwy 25R at Twy B sometimes fail to comply. Pilots sometimes land on Rwy 25R without clearance. Pilots instructed to hold short of Rwy 25L at Twy C sometimes fail to comply. Pilots instructed to hold short of Rwy 07L at Twy H sometimes fail to comply. Pilots instructed to hold short of Rwy 07R at Twy G sometimes fail to comply. Pilots instructed to hold short of Rwy 25R at Twy G sometimes fail to comply. Pilots may be confused at the intersections of Twy J, Twy A, and Twy G sometimes fail to comply with taxi instructions.